

ERA25LA251

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of airplane looking aft. (Courtesy of FAA)



Photograph 2 - View of airplane upside down. (Courtesy of Pilot)



Photograph 3 - Left wing damage. (Courtesy of Pilot)



Photograph 4 - View of muddy ground track leading up to wreckage. (Courtesy of Pilot)