

ERA25LA259

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Forward view of upright post-crash fire damaged helicopter.
(Courtesy of FAA)**



**Photograph 2 - Right-side view of upright post-crash fire damaged helicopter.
(Courtesy of FAA)**



**Photograph 3 - Aft view of upright post-crash fire damaged helicopter.
(Courtesy of FAA)**



**Photograph 4 - Left-side view of post-crash fire damaged helicopter.
(Courtesy of FAA)**



**Photograph 5 - View of post-crash fire damaged engine.
(Courtesy of FAA)**



**Photograph 6 - View of fire damaged fuel lines.
(Courtesy of FAA)**