

ERA25LA267

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of damage to the tail boom. (Courtesy of FAA)**



**Photograph 2 - View of the helicopter at accident site. (Courtesy of Pilot)**