

ERA25LA271

INVESTIGATION PHOTOGRAPHS



Photograph 1 – Airplane overview at accident site (Source: Pilot)



Photograph 2 – Airplane overview at accident site (Source: Pilot)



Photograph 3 – Damage to the right wing (Source: Pilot)



Photograph 4 – Damage to the left wing (Source: Pilot)