

ERA25LA282

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Bottom View of the Helicopter Resting on Its Left Side (Courtesy of FAA)



Photograph 2 - Top View of the Helicopter Resting on Its Left Side (Courtesy of FAA)



Photograph 3 - View Showing Damage to the Tailboom (Courtesy of FAA)