

ERA25LA311

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Lower Forward Fuselage Damage (Courtesy of FAA)



Photograph 3 - Upper Forward Fuselage Damage (Courtesy of FAA)