

ERA25LA317

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of airplane off side of runway 03.
(Courtesy of FAA)**



**Photograph 2 - View of underside of right wing bent tip.
(Courtesy of FAA)**



**Photograph 3 - View of topside of right wing bent tip.
(Courtesy of FAA)**