

ERA25LA322

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Airplane at accident site (Source: FAA)**



**Photograph 2 - Airplane after recovery (Source: FAA)**



**Photograph 3 - Damage to the left wing (Source: FAA)**



**Photograph 4 - Damage to the left wing (Source: FAA)**