

ERA25LA323

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Firewall Damage (Courtesy of FAA)



Photograph 2 - Floor Damage (Courtesy of FAA)