

ERA25LA325

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left horizontal stabilizer accident damage (Courtesy of FAA)



Photograph 2 - Left horizontal stabilizer accident damage (Courtesy of FAA)



Photograph 3 - Left horizontal stabilizer accident damage (Courtesy of FAA)