

ERA25LA341

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane, postaccident with separated left wing (Courtesy of FAA)



Photograph 2 - Left forward fuselage accident damage with breached hull (Courtesy of FAA)



Photograph 3 - Left wing separation accident damage (Courtesy of FAA)



Photograph 4 - Left forward fuselage accident damage (Courtesy of FAA)



Photograph 5 - Right forward fuselage and hull accident damage (Courtesy of FAA)