

ERA25LA343

INVESTIGATION PHOTOGRAPHS



Photograph 1 – Airplane at accident site (Photo Source: of St. Pete Air)



Photograph 2 – Damage to fuselage (Photo Source: St. Pete Air)



Photograph 3 – Damage to fuselage (Photo Source: St. Pete Air)



Photograph 4 – Damage to airplane (Photo Source: St. Pete Air)



Photograph 5 - Damage to fuselage (Photo Source: St. Pete Air)



Photograph 6 – Cropped still image from surveillance camera of accident airplane on approach (Photo Source: St. Pete Air)