

ERA25LA349

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N272BH Pipistrel (Courtesy of FAA)



Photograph 2 - Left Wing Impact with Parked Aircraft (Courtesy of FAA)



Photograph 3 - Right Wing Damage, Impact with Tree (Courtesy of FAA)