

ERA25LA354

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage in Tree (Courtesy of FAA)



Photograph 2 - Right Wing Damage (Courtesy of FAA)



Photograph 3 - Main Wreckage Recovered (Courtesy of Anglin Aircraft Recovery)