

ERA25LA359

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N4779M Rollover (Courtesy of FAA)



Photograph 2 -Damage Rear View (Courtesy of FAA)



Photograph 3 - Rudder/Horizontal Stabilizer Damage (Courtesy of FAA)