

ERA25LA364

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left Side of Main Wreckage (Courtesy of Pilot)



Photograph 2 - Right Side of Main Wreckage (Courtesy of Pilot)