

ERA25LA377

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Wing Damage (Courtesy of Operator)



Photograph 2 - Right Wing Rib Damage (Courtesy of Operator)