


ERA25LA382

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Photograph of Accident Airplane (Source: Aircraft.Com)



Photograph 2 - Accident Scene with Airplane in the Water (Courtesy of Owner)



Photograph 3 - Cracking Damage to Engine Pylon (Courtesy of Owner)



Photograph 4 - Close up of Damage to Engine Pylon (Courtesy of Owner)