

ERA26FA035

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Helicopter (Source: NTSB)



Photograph 2 - Empennage Damage (Source: NTSB)



Photograph 3 - Fenestron Damage (Source: NTSB)



Photograph 4 - Main Rotor Damage (Source: NTSB)



Photograph 5 - Fuselage/Cabin Damage (Source: NTSB)



Photograph 6 - Damage to Underside of Helicopter (Source: NTSB)