


ERA26LA018

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left side view of airplane damage. (Courtesy of FAA)



Photograph 2 - View of left side of airplane showing airframe and engine compartment damage. (Courtesy of FAA)



Photograph 3 - View of left wing damage (Courtesy of FAA)