

ERA26LA025

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Ground Collision Between N825KS (High-Wing) and N202RD (Low-Wing)  
(Courtesy of Boca Raton Airport)**



**Photograph 2 - Low-Wing Airplane Beneath High-Wing (Courtesy of Boca Raton Airport)**



**Photograph 3 - Airport CCTV of Accident (Courtesy of Boca Raton Airport)**



**Photograph 4 - N825KS Left Wing Leading Edge, Spar and Rib Damage (Courtesy of FAA)**



**Photograph 5 - N202RD Propeller Damage (Courtesy of Boca Raton Airport)**