

ERA26LA033

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at Rest in Hillside (Courtesy of FAA, Annotated by NTSB)



Photograph 2 - Outboard Right Wing Leading Edge Damage with Brush (Courtesy of FAA)



Photograph 3 - Left Wing Leading Edge Damage (Courtesy of FAA)



Photograph 4 - Interior Paneling and Fuselage Damage (Courtesy of FAA)