

ERA26LA044

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Wreckage in Swamp Adjacent to F47 (Courtesy of Cirrus Aircraft)



Photograph 2 - Airplane Forward Fuselage Damage and Broken Landing Gear (Courtesy of Cirrus Aircraft)



Photograph 3 - Airplane Empennage Damage (Courtesy of Cirrus Aircraft)