

ERA26LA083

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Photograph of Accident Aircraft (Courtesy of FAA)



Photograph 2 - Damage to Nose Landing Gear Doors (Courtesy of FAA)



Photograph 3 - Damage to Lower Fuselage (Courtesy of FAA)