

ERA26LA142

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of left wing damage caused by bird strike. (Courtesy of Operator)



Photograph 2 - Bird strike damage to left leading edge. (Courtesy of Operator)