

ERA26LA143

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage to the right wing (Source: Wings of Carolina)



Photograph 2 - Damage to the right wing (Source: Wings of Carolina)



Photograph 3 - Damage to the right wing (Source: Wings of Carolina)



Photograph 4 - Damage to the right wing (Source: Wings of Carolina)



Photograph 5 - Damage to the right wing (Source: Wings of Carolina)



Photograph 6 - Damage to the right wing (Source: Wings of Carolina)