

ERA26LA157

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wreckage overview (Source: Cirrus Aircraft)



Photograph 2 - Wreckage overview (Source: Cirrus Aircraft)



Photograph 3 - Wreckage overview (Source: Cirrus Aircraft)



6

Photograph 4 - Empennage overview (Source: Cirrus Aircraft)



Photograph 5 - Runway and fire ant nest (Source: Cirrus Aircraft)



Photograph 6 - Fire ant nest on runway (Source: Cirrus Aircraft)