

ERA26LA212

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View from the nose showing impact point and inverted airplane (Courtesy of FAA)**



**Photograph 2 - Right-hand side view showing damage to fuselage and right wing (Courtesy of FAA)**



**Photograph 3 - Left-hand side view showing damage to empennage (Courtesy of FAA)**