

ERA26LA240

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of outboard right-wing spar. (Courtesy of FAA)



Photograph 2 - Close up of bent spar. (Courtesy of FAA)