

ERA26LA255

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left Side View of Airplane at Accident Site (Courtesy of FAA)



Photograph 2 - Aft View Looking Forward of Airplane at Accident Site (Courtesy of FAA)



Photograph 3 - Right Side View of Airplane at Accident Site (Courtesy of FAA)