

ERA26LA259

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Inverted on Runway with Trail of Crop Debris (Courtesy of FAA)



Photograph 2 - Close up of Inverted Airplane Showing Damage to Vertical Fin, Rudder and Wing Struts (Courtesy of FAA)