

ERA26LA263

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front of the Airplane On-Scene with Engine Mount, Fuselage, and Right Wing Damage



Photograph 2 - Right Wing Forward Inboard Damage



Photograph 3 - View of the Airplane On-scene with Fuselage Damage