

ERA26LA276

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Aircraft (Source: FAA)



Photograph 2 - Damage to Empennage (Source: FAA)



Photograph 3 - Damage to Left Lower Wing and Elevator (Source: FAA)



Photograph 4 - Damage to Elevator (Source: FAA)



Photograph 5 - Damage to Left Lower Wing (Source: FAA)