


ERA26LA282

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N291CA (Courtesy of Pilot)



Photograph 2 - Substantial damage to right wing (Courtesy of FAA)