


ERA26LA311

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the glider at the accident site. (Courtesy of Ohio State Highway Patrol)



Photograph 2 - View of the glider at the accident site. (Courtesy of Ohio State Highway Patrol)