

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Caldwell State: ID

ZIP: 83605 Country: USA

Latitude: 43 38' 37"N Longitude: 116 38' 25"W

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 07/13/2015 Local Time: 3:00 pm

mm/dd/yyyy

Time Zone: Mountain

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N184SH

Manufacturer: Robinson

Model: R22 Beta II

Serial Number: 4207

Year of Manufacture: 2007

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Make: _____
☐ Original Design

- ☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 1370 lbs

Weight at Time of Accident/Incident: 1290 lbs

Number of Seats: 2 Flight Crew Seats: _____

Cabin Crew Seats: _____ Passenger Seats: _____

Number of Engines: 1

Category of Aircraft

- ☐ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☒ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate (Check all that apply)

- Standard** **Special**
☒ Normal ☐ Restricted
☐ Aerobatic ☐ Limited
☐ Balloon ☐ Provisional
☐ Commuter ☐ Special Flight
☐ Transport ☐ Experimental
☐ Utility ☐ Special Light-Sport
☐ Experimental Light-Sport
☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

- ☐ Retractable
☐ Tricycle ☐ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☒ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

- ☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Serial	Manufacturer's Serial Number	Date of Mfg. <u>mm/dd/yyyy</u>	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Lycoming	O-360-J2A	L-40881-36E	06/06/2007	145BHP	1072.5	9.0	1072.5 SI
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AATP ☐ Conditional Inspection
☒ Annual ☐ Unknown

Date Last Inspection: 07/11/2015

mm/dd/yyyy

Airframe Total Time: 1072.5 hrs

hours measured at (Select one)

☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☐ Annual
☐ Conditional (Amateur-built only)
☒ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
☒ Specify: Hand held

Propeller 1

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: Pointer

Model or Part No.: 3000-10

TSO No.: ☐ C91 (121.5 MHz) ☒ C91a (121.5 MHz)
☐ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☒ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☒ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☒ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☐ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Threshold Aviation LLCCity: MeridianState: IDZIP: 83642Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: USA**Operator of Aircraft**☐ Same As Registered Owner☐ Same Address as Registered OwnerName: Alpine Aviation LLCCity: Caldwell

Doing Business As: _____

State: IDZIP: 83605

Air Carrier/Operator Designator (4 Character Code): _____

Country: USA**Operating Certificates Held**

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
 Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437

- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial

☐ Public Aircraft (Select one)

- ☐ Armed Forces
☐ Federal
☐ State
☐ Local

☐ Unknown**Revenue Operation for FAR 121, 125, 129, 135**

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International

- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☒ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☐ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: Caldwell Industrial AirportDistance From Airport Center: 125 smAirport Identifier: KEULDirection From Airport: 270 degrees trueProximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/AAirport Elevation: 2430 ft. msl**Runway Information**Runway ID: 12/30 (L/R/C) Length: 5000 ft Width: 100 ft**Runway/Landing Surface (Check all that apply)**

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☒ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Final ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)☒ None

- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)☐ None

- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☒ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION**"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident**

☐ Pilot ☐ Co-Pilot ☐ Student Pilot ☒ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Kevin

City of Residence: Boise

Middle Initial: J

State: ID ZIP: 83709

Last Name: Sleaff

Country: USA

Age at time of Accident/Incident: 38 Date of Birth: mm/dd/yyyy

Certificate Number: mm/dd/yyyy

Degree of Injury

☒ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☒ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available
☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used
☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☒ Flight Instructor ☒ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☒ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☒ Class 2 ☐ Unknown

Medical Certificate Validity

☒ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

12/01/2014
mm/dd/yyyy

Medical Certificate Limitations**Medical Certificate Special Issuance****Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:**

01/03/2015
mm/dd/yyyy

Flight Review Aircraft

Make: Robinson

Model: R22 Beta II

Airplane Rating(s) (Check all that apply)

☒ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☒ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☐ Airplane
☒ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multi-Engine ☒ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings**Student Endorsements (Include dates)**

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	2,800	1,800			256		82	2,800		
Pilot in Command (PIC)	2,750	1,750			253		82	2,750		
Time as Instructor	2,171	1,500			200		30	2,171		
This Make/Model					100		0			
Last 90 Days	150	100			50		15	150		
Last 30 Days	50	40			20		5	50		
Last 24 Hours	3	3			0		0	3		

"FLIGHT CREWMEMBER 2" INFORMATION**"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident**

☐ Pilot ☐ Co-Pilot ☒ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: Patrick

City of Residence: Boise

Middle Initial: A

State: ID ZIP: 83705

Last Name: Burns

Country: USA

Age at time of Accident/Incident: 39 Date of Birth: mm/dd/yyyy

Certificate Number: mm/dd/yyyy

Degree of Injury

☒ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☒ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available
☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used
☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☒ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☐ Pilot
☒ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☒ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☒ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

01/21/2015
 mm/dd/yyyy

Medical Certificate Limitations

Must wear corrective lenses

Medical Certificate Special Issuance

**Date of Last Flight Review
or Equivalent, Including
FAR 121/135 Checks:**

mm/dd/yyyy

Flight Review Aircraft

Make: _____

Model: _____

Airplane Rating(s)

(Check all that apply)
☒ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)
☒ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)
☒ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)
☒ None
☐ Airplane Single-Engine
☐ Airplane Multi-Engine
☐ Gyroplane
☐ Powered Lift
☐ Instrument Airplane
☐ Instrument Helicopter
☐ Helicopter
☐ Glider
☐ Sport

Type Ratings**Student Endorsements (Include dates)**

SFAR 73 Awareness training - 4/24/15
 Solo Endorsement - 5/4/15
 Solo X country - 6/3/15
 Solo X country flight plan - 6/3/15

**Flight Time (Enter appropriate
number of hours in each box)**

All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
					Actual	Simulated			
Total Time	94	94		3			94		
Pilot in Command (PIC)	10	10		0			10		
Time as Instructor	0	0		0			0		
This Make/Model				3					
Last 90 Days	78	78		3			78		
Last 30 Days	13	13		0			13		
Last 24 Hours	2	2		0			2		

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew; complete the following information)						
Crew Name and Address			Seat Occupied		Injury	
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____			☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Private ☐ Recreational ☐ Student ☐ Sport ☐ Commercial ☐ US Military ☐ Airline Transport ☐ Foreign ☐ Flight Engineer			Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs				
Crew Name and Address			Seat Occupied		Injury	
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____			☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Private ☐ Recreational ☐ Student ☐ Sport ☐ Commercial ☐ US Military ☐ Airline Transport ☐ Foreign ☐ Flight Engineer			Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs				
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)						
Name and Address		Seat	Injury	Restraint Type		Inflatable Restraints
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>KEUL</u> City: <u>Caldwell</u> State: <u>ID</u> Country: <u>USA</u>	Time of Departure Time: <u>2:30 pm</u> Time Zone: <u>Mountain</u>	Destination Airport ID: <u>KEUL</u> City: <u>Caldwell</u> State: <u>ID</u> Country: <u>USA</u>	Type Flight Plan Filed ☒ None ☐ Company VFR ☐ Military VFR ☐ VFR ☐ VFR/IFR ☐ IFR ☐ Unknown Activated? ☐ Yes ☐ No ☐ Unknown
--	--	---	--

Type of ATC Clearance/Service (Check all that apply)

☒ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☐ VFR	☐ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class B ☐ Class C ☐ Class D ☐ Class E ☐ Class G	☒ Class G ☐ Demo Area ☐ Warning Area ☐ Prohibited Area ☐ Restricted Area	☐ Military Operations Area (MOA) ☐ Airport Advisory Area ☐ Jet Training Area ☐ TRSA ☐ FAR 93	☐ Special ☐ Air Traffic Control Area ☐ Unknown	Altitude of In-Flight Occurrence: _____ ft msl
--	--	---	---	--

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE**Source of Pilot Weather Information**

(Check all that apply)

☐ National Weather Service	☐ Company
☐ Flight Service Station	☐ Military
☐ TV/Radio	☐ Internet
☒ Automated Report	☐ None
☐ Commercial Weather Service (DUATS)	☐ Unknown
☐ On-Board Weather	

Weather Observation Facility

Facility ID: <u>135.075</u>
Observation Time: <u>3:00 pm</u>
Time Zone: <u>Mountain</u>
Distance from Accident Site: <u>.5</u> nm
Direction from Accident Site: <u>090</u> degrees true

Basic Conditions
☒ VMC
☐ IMC
☐ Unknown
Light Condition
☐ Dawn
☐ Day
☐ Dusk
☐ Night
☐ Dark Night
☐ Bright Night
☐ Unknown
Sky/Lowest Cloud Condition
☐ Clear
☐ Few
☐ Partial Obscuration
☐ Scattered
☐ Thin Broken
☐ Thin Overcast
☐ Unknown
Ceiling
☒ None (Clear)
☐ Broken
☐ Overcast
☐ Obscured
☐ Indefinite
☐ Unknown
Temperature: 24 (C) or _____ (F)Dew Point: 5 (C) or _____ (F)Altimeter Setting: 30.15 in. Hg
or _____ MB**Lowest Cloud Condition Height**

_____ ft agl

Ceiling Height

_____ ft agl

Wind Direction☒ Variable-or-
Direction: 120 degrees true**Wind Speed**☐ Calm
☒ Light and Variable-or-
Speed: 9-11 kts**Wind Gusts**☒ Not Gusting-or-
Speed: _____ kts

Visibility _____ miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: _____ ft

Intensity of Precipitation
☐ Light
☐ Moderate
☐ Heavy
☐ N/A
☐ Unknown
Type of Precipitation (Check all that apply)

☒ None	☐ Drizzle	☐ Freezing Rain
☐ Rain	☐ Ice Pellets	☐ Snow Shower
☐ Snow	☐ Snow Pellets	☐ Ice Pellets Shower
☐ Hail	☐ Snow Grains	☐ Freezing Drizzle
☐ Rain Showers	☐ Ice Crystals	

Restriction to Visibility (Check all that apply)

☒ None	☐ Fog
☐ Blowing Dust	☐ Ground Fog
☐ Blowing Sand	☐ Haze
☐ Blowing Snow	☐ Ice Fog
☐ Blowing Spray	☐ Smoke
☐ Dust	☐ Unknown

Icing Forecast

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Icing Actual

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Turbulence

Type (Check all that apply)	Severity
☒ None	☐ Light
☐ Clear Air	☐ Moderate
☐ Terrain-Induced	☐ Severe
☐ Convective Turbulence	☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

DAMAGE TO AIRCRAFT AND OTHER PROPERTY

Aircraft Damage		Aircraft Fire		Aircraft Explosion	
☐ None	☒ Substantial	☐ None	☐ Both Ground and In-Flight	☒ None	☐ Both Ground and In-Flight
☐ Minor	☐ Destroyed	☐ In-Flight	☐ Fire at Unknown Time	☐ In-Flight	☐ Explosion at Unknown Time
	☐ Unknown	☐ On-Ground	☐ Unknown	☐ On-Ground	☐ Unknown

Description of Damage to Aircraft and Other Property (Use additional sheet if necessary)

Main rotor blade made contact with Tailcone, separating it just aft of the strobe light.

NARRATIVE HISTORY OF FLIGHT (Please type or print in ink)

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

The purpose of the flight was for flight instruction. We departed approximately 2:30 pm Mountain. The entire flight was conducted at the airport, (KEUL), using taxiway A parallel runway 12. The local AWOS was reporting winds 120 at 9 kts and allimeter of 30.15. We started off with some basic maneuvers, normal approach, air taxi, rapid deceleration, and some slopes. We then moved on to a straight-in practice autorotation power-on recovery. AWOS was reporting 110-120 at 9-11 kts after checking it a few times. The student performed two straight-in auto's with power on recovery, with little to no assistance. These maneuvers were performed towards the east end of the taxiway at J and A Intersection. The student proceeded to set up for a 180 degree practice auto with power on recovery. The student performed the maneuver well, I did catch a possible rotor overspeed, and the student did balloon up at the recovery stage of the auto, but was to be expected by the current wind and pressure. The student performed another 180 degree practice auto with no assistance necessary. He did however balloon up again at the recovery/flare stage. I then demonstrated a 180 degree auto to the student. All three of the last auto's were executed at the east end of the taxiway. The student then prepared for another 180 degree practice auto power on recovery. We checked the AWOS again in the downwind, still reporting 120 at 10kts. I remember the student climbed a little while listening to the AWOS and thus we were also shooting for the west end of the airport. The student entered the auto at approximately 850 AGL (3350 MSL). He established the auto and turned right away, he leveled out after turning 90 degrees and we could feel the wind pushing us. He then turned another 90 degrees and lined us up with the taxiway. I commented on how the student caught the rotor RPM's from overspeeding and maintained good airspeed, (70-73kts). We were approximately 300 ft AGL and I commented that everything looks good and "its just a straight-in auto from here." At approximately 200 ft AGL the student nosed forward with the cyclic, I attempted to fix it with aft cyclic, but the student already started to level the aircraft. At that time we had approximately 70kts airspeed and the rotor RPM's were above the green (104-106%). I anticipated a charge but the RPM's remained. At this time we were falling through approximately 100 ft AGL. The student proceeded to roll the throttle up and I heard the engine RPM's raise and I saw the engine tach go above 80%. At the same time he started to flare and raised the collective as if he was anticipating a charge. That's when the aircraft fell dramatically and began to shake. I was already shadowing the controls at this time and came on attempting to decrease our decent rate, and downwash. I immediately lowered collective, afted the cyclic, and continued to roll the throttle up. It was as if we not only lost any and all headwind, but were being forced to the ground by either a tail wind or our own down wash, or a combination of both. Once I realized the engine was not increasing the RPM's, I continued to increase the flare with the cyclic until approximately 20 ft AGL where I began to level the aircraft. Once I felt it was level enough I raised the collective prior to contacting the ground. I immediately lowered collective after we were on the taxiway to slow our ground run. It did not seem as though the landing was very hard, but still had forward ground run. As we proceeded down the taxiway the aircraft yawed left, I input right pedal and we somehow came around to the right. We also were drifting to the right and I input left cyclic in an attempt to stay on the taxiway. As the aircraft slowed down and came to a stop, it spun to the right 180 degrees as the left skid vacated the taxiway into the dirt. We were then facing the opposite direction from which we came in. The engine was idling and main rotors were still turning. After asking the student if he was ok, I stopped the engine and that is when I realized that the tail cone had been separated. The empennage was on the taxiway approximately 30 ft in front of us. After the rotor blades came to a stop we released our seat belts and exited the aircraft.

RECOMMENDATION (How could the situation/handling have been improved?)**Operator/Owner Safety Recommendation**

I feel that if there was a wind indicator at the intersection of Intended landing, I could have been more aware of any sudden wind changes, but at the point at which the extreme descent occurred, I'm not sure what else could have been done to prevent the outcome.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No
(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION

Fuel on Board at Last Takeoff
(Convert from pounds, as necessary)

8 _____ Gallons

Fuel Type

☐ 80/87

☐ 115/145

☐ Jet B

☐ Other, specify _____

☒ 100 Low Lead

☐ Jet A

☐ JP8

☐ 100/130

☐ Jet A-1

☐ Automotive

Other Services, if Any, Prior to Departure

EVACUATION OF AIRCRAFT

Was an emergency evacuation of the aircraft performed? ☐ Yes ☒ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

We removed seat belts and exited the aircraft. One occupant exited out the left and the other exited out the right.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed

☐ Minor

☐ Substantial

☐ None

Registered Owner of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

7/14/2015

mm/dd/yyyy

Name of Pilot/Operator: Kevin Slelaff

Signature: _____

-- or -- ☒ Check here to electronically sign this document**If a Person Other than Pilot/Operator is Filing Report**

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document**FOR NTSB USE ONLY**NTSB Accident/Incident No.
GAA15CA181Reviewed by NTSB Regional Office
GAAName of Investigator
Michael J. HodgesDate Report Received
07/21/2015