

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: U77 Spanish Fork/Springville Arpt State: UT

ZIP: 84660 Country: USA

Latitude: 40-08-33.5100N Longitude: 111-39-51.4200W

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 08/05/2015 Local Time: 0820
mm/dd/yyyy

Time Zone: Mountain

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N560JF

Manufacturer: Cessna

Model: Citation XL CE560XL

Serial Number: 5173

Year of Manufacture: 2001

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

☒ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 20000 lbs

Weight at Time of Accident/Incident: 19000 lbs

Number of Seats: 10 Flight Crew Seats: 2

Cabin Crew Seats: 0 Passenger Seats: 8

Number of Engines: 2

Category of Aircraft

- ☒ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☐ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
- ☐ Aerobatic
- ☐ Balloon
- ☐ Commuter
- ☒ Transport
- ☐ Utility

Special

- ☐ Restricted
- ☐ Limited
- ☐ Provisional
- ☐ Special Flight
- ☐ Experimental
- ☐ Special Light-Sport
- ☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☒ Retractable

- ☒ Tricycle ☐ Tailwheel
- ☐ Amphibian ☐ High Skid
- ☐ Emergency Float ☐ Skid
- ☐ Float ☐ Ski
- ☐ Hull ☐ Ski/Wheel
- ☐ Other Launch/Recovery System
- ☐ None ☐ Unknown

Engine Type (Select one)

- ☐ Reciprocating ☐ Liquid Rocket
- ☐ Turbo Shaft ☐ Solid Rocket
- ☐ Turbo Prop ☐ Hybrid Rocket
- ☐ Turbo Jet ☐ None
- ☒ Turbo Fan ☐ Unknown
- ☐ Electric

Fuel System Type (Reciprocating)

- ☐ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☐ Horsepower or ☒ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Pratt & Whitney	PW545A	DB0692	N/A	3804	4173	1673	4173
Eng. 2	Pratt & Whitney	PW545A	DB0689	N/A	3804	4173	1673	4173
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☒ Continuous Airworthiness
- ☐ AAIP ☐ Conditional Inspection
- ☐ Annual ☐ Unknown

Date Last Inspection: 07/11/2015
mm/dd/yyyy

Airframe Total Time: 4022 hrs

hours measured at (Select one)

☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☐ Annual
- ☐ Conditional (Amateur-built only)
- ☒ Manufacturer's Inspection Program
- ☐ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
- ☒ Specify: Engine fire bottle/cabin and cockpit fire extinguishers

Propeller 1

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____

Model: _____

Propeller 2

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: Artex

Model or Part No.: C406N 453-5060

TSO No.: ☐ C91 (121.5 MHz) ☐ C91a (121.5 MHz)
☒ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☒ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☒ No

If not activated:

- Indicate Reason:
- ☐ Impact Damage
 - ☐ Fire Damage
 - ☐ Battery Expired/Damaged
 - ☒ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
- ☐ Airframe Parachute
- ☒ Angle of Attack Indicator
- ☒ Autopilot
- ☐ Data Recorder
- ☒ Electronic Flight Bag or Handheld Device
- ☒ Electronic Multifunction Display
- ☒ Electronic Primary Flight Display
- ☐ Handheld GPS
- ☐ Heads Up Display
- ☒ Onboard Weather
- ☐ Satellite Tracking Device
- ☒ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Snow Peak Ventures LLC/Clyde Companies IncCity: Spanish ForkState: UTZIP: 85660Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: USA**Operator of Aircraft**☒ Same As Registered Owner☐ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☐ Personal
☒ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: Spanish Fork/Springville AirportDistance From Airport Center: 1 smAirport Identifier: U77Direction From Airport: 300 degrees trueProximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/AAirport Elevation: 4525 ft. msl**Runway Information**Runway ID: 12 (L/R/C) Length: 5700 ft Width: 100 ft**Runway/Landing Surface (Check all that apply)**

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☒ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☒ None
- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

Middle Initial: C State: UT ZIP: 84651

Last Name: Ringger Country: USA

Age at time of Accident/Incident: 36 Date of Birth: *mm/dd/yyyy*

Certificate Number: [REDACTED]

Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious		Seat Occupied ☒ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single		Restraint Type Available ☐ None ☐ Lap only ☐ 3-point ☐ 4-point ☒ 5-point ☐ Unknown Used ☐ None ☐ Lap only ☐ 3-point ☐ 4-point ☒ 5-point ☐ Unknown		Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	
Pilot Certificate(s) <i>(Check all that apply)</i> ☐ None ☒ Flight Instructor ☒ Commercial ☐ US Military ☐ Private ☐ Recreational ☒ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer							
Principal Occupation ☒ Pilot ☐ Other ☐ Unknown		Medical Certificate ☐ None ☐ Class 3 ☒ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown		Medical Certificate Validity ☐ Without limitations/waivers ☐ Unknown ☒ With limitations/waivers ☐ N/A ☐ Special Issuance		Date of Last Medical <u>01/18/2015</u> <i>mm/dd/yyyy</i>	

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: <u>09/18/2014</u> <i>mm/dd/yyyy</i>	Flight Review Aircraft Make: <u>Cessna</u> Model: <u>Citation Excel</u>
---	--

Airplane Rating(s) (Check all that apply)	Other Aircraft Rating(s) (Check all that apply)	Instrument Rating(s) (Check all that apply)	Instructor Rating(s) (Check all that apply)
☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☒ Multiengine Land ☐ Multiengine Sea	☒ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	☐ None ☒ Airplane ☐ Helicopter ☐ Powered Lift	☐ None ☒ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport

Type Ratings	Student Endorsements <i>(Include dates)</i>
DO-228 CE560XL	

Flight Time <i>(Enter appropriate number of hours in each box)</i>	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	4,820	740	361	4,459	410	310	108			
Pilot in Command (PIC)	2,995	525	323	2,672						
Time as Instructor	23		23							
This Make/Model					54	51				
Last 90 Days	36	36		36	6	3				
Last 30 Days	12	12	0	12	2	1				
Last 24 Hours	0	0	0	0	0	0				

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident ☐ Pilot ☒ Co-Pilot ☐ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew										
"Flight Crewmember 2" was pilot flying ☐ Yes ☒ No										
"Flight Crewmember 2" Identification First Name: <u>Thomas</u> Middle Initial: <u>O</u> Last Name: <u>Cook</u> Age at time of Accident/Incident: <u>37</u> Date of Birth: <u> </u> <i>mm/dd/yyyy</i> Certificate Number: <u> </u>						City of Residence: <u>Moroni</u> State: <u>UT</u> ZIP: <u>84646</u> Country: <u>USA</u>				
Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious		Seat Occupied ☐ Left ☐ Front ☐ Unknown ☒ Right ☐ Rear ☐ Center ☐ Single		Restraint Type Available ☐ None ☐ Lap only ☐ 3-point ☐ 4-point ☒ 5-point ☐ Unknown Used ☐ None ☐ Lap only ☐ 3-point ☐ 4-point ☒ 5-point ☐ Unknown			Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown			
Pilot Certificate(s) <i>(Check all that apply)</i> ☐ None ☐ Private ☐ Student ☒ Flight Instructor ☐ Recreational ☐ Sport ☒ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign										
Principal Occupation ☒ Pilot ☐ Other ☐ Unknown		Medical Certificate ☐ None ☐ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☒ Class 2 ☐ Unknown		Medical Certificate Validity ☐ Without limitations/waivers ☐ Unknown ☒ With limitations/waivers ☐ N/A ☐ Special Issuance			Date of Last Medical <u>02/14/2014</u> <i>mm/dd/yyyy</i>			
Medical Certificate Limitations Must wear corrective lenses										
Medical Certificate Special Issuance										
Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: <u>09/18/2014</u> <i>mm/dd/yyyy</i>			Flight Review Aircraft Make: <u>Cessna</u> Model: <u>Citation Excel</u>							
Airplane Rating(s) <i>(Check all that apply)</i> ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☒ Multiengine Land ☐ Multiengine Sea		Other Aircraft Rating(s) <i>(Check all that apply)</i> ☒ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift		Instrument Rating(s) <i>(Check all that apply)</i> ☐ None ☒ Airplane ☐ Helicopter ☐ Powered Lift		Instructor Rating(s) <i>(Check all that apply)</i> ☐ None ☒ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☒ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport				
Type Ratings SIC only CE 560XL						Student Endorsements <i>(Include dates)</i>				

Flight Time <i>(Enter appropriate number of hours in each box)</i>	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	2,361	576	1,245	1,116	199	68	90			
Pilot in Command (PIC)	1,150	0	1,125	25						
Time as Instructor	850		850							
This Make/Model										
Last 90 Days	45	45								
Last 30 Days	25	25								
Last 24 Hours	0	0	0	0						

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: <u>Stephanie</u> City : _____ Middle Initial: _____ State: <u>UT</u> ZIP: _____ Last Name: <u>Murphy</u> Country: <u>USA</u> ☐ Crew ☒ Passenger ☐ Other			☐ Left ☐ Center ☒ Right ☐ Unknown Row: <u>2</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☒ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>U77</u> City: <u>Spanish Fork</u> State: <u>UT</u> Country: <u>USA</u>	Time of Departure Time: <u>0815</u> Time Zone: <u>MDT</u>	Destination Airport ID: <u>KSGU</u> City: <u>St George</u> State: <u>UT</u> Country: <u>USA</u>	Type Flight Plan Filed ☐ None ☐ Company VFR ☐ Military VFR ☐ VFR ☐ VFR/IFR ☒ IFR ☐ Unknown Activated? ☐ Yes ☒ No ☐ Unknown
---	--	--	---

Type of ATC Clearance/Service (Check all that apply)

☐ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☐ VFR	☒ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class B ☐ Class C ☐ Class D ☐ Class E	☒ Class G ☐ Demo Area ☐ Warning Area ☐ Prohibited Area ☐ Restricted Area	☐ Military Operations Area (MOA) ☐ Airport Advisory Area ☐ Jet Training Area ☐ TRSA ☐ FAR 93	☐ Special ☐ Air Traffic Control Area ☐ Unknown	Altitude of In-Flight Occurrence: _____ ft msl
--	--	---	---	--

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☒ National Weather Service ☒ Flight Service Station ☒ TV/Radio ☒ Automated Report ☒ Commercial Weather Service (DUATS) ☐ On-Board Weather	☐ Company ☐ Military ☒ Internet ☐ None ☐ Unknown
---	--

Weather Observation Facility

Facility ID: KPVU
 Observation Time: 1459Z
 Time Zone: MDT
 Distance from Accident Site: 5 nm
 Direction from Accident Site: 300 degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn
☒ Day
☐ Dusk
☐ Night
☐ Dark Night
☐ Bright Night
☐ Unknown

Sky/Lowest Cloud Condition

☐ Clear
☒ Few
☐ Partial Obscuration
☐ Scattered
☐ Thin Broken
☐ Thin Overcast
☐ Unknown

Lowest Cloud Condition Height

12000 ft agl

Ceiling

☒ None (Clear)
☐ Broken
☐ Overcast
☐ Obscured
☐ Indefinite
☐ Unknown

Ceiling Height

_____ ft agl

Temperature: 24 (C) or _____ (F)

Dew Point: 9 (C) or _____ (F)

Altimeter Setting: 3005 in. Hg
or _____ MB

Wind Direction

☐ Variable

-or-
Direction: 130 degrees true

Wind Speed

☐ Calm
☐ Light and Variable

-or-
Speed: 10 kts

Wind Gusts

☒ Not Gusting

-or-
Speed: _____ kts

Visibility 15 miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: _____ ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None	☐ Drizzle	☐ Freezing Rain
☐ Rain	☐ Ice Pellets	☐ Snow Shower
☐ Snow	☐ Snow Pellets	☐ Ice Pellets Shower
☐ Hail	☐ Snow Grains	☐ Freezing Drizzle
☐ Rain Showers	☐ Ice Crystals	

Restriction to Visibility (Check all that apply)

☒ None	☐ Fog
☐ Blowing Dust	☐ Ground Fog
☐ Blowing Sand	☐ Haze
☐ Blowing Snow	☐ Ice Fog
☐ Blowing Spray	☐ Smoke
☐ Dust	☐ Unknown

Icing Forecast

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Icing Actual

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Turbulence

Type (Check all that apply)	Severity
☒ None	☐ Light
☐ Clear Air	☐ Moderate
☐ Terrain-Induced	☐ Severe
☐ Convective Turbulence	☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

CDC 08/011 U77 RWY 12 THR DISPLACED 800FT. DECLARED DISTANCES: TORA
 4900FT TODA 4900FT ASDA 4900FT LDA 4900FT.
 CDC 08/013 U77 TWY A3, A4, A5 CLSD
 CDC 08/012 U77 TWY A BTN TWY A3 AND TWY A5 CLSD

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Damage to Left Wing, 2-3 feet from the edge estimated to be in 1 foot of width. Left wing contacted a stationary trencher/tractor located about 10 feet from the edge of the taxiway.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

N560JF Citation Excel

Location-Spanish Fork, UT Airport U77

Taxiway A near the approach end of RWY 12

Left Wing tip struck a trencher- approximately 2-3 feet from the leading edge of the left wing tip.

PIC-Jared Ringger SIC- Thomas Cook

1 passenger on board

No injuries

On August 5, 2015 at approximately 0820 am Citation Excel N560JF came into contact with a stationary trencher/tractor. The airplane was taxiing on Taxiway A at U77. At the time of the incident surface conditions were dry and weather was partly cloudy with scattered high clouds. After fueling around 730 am on 8/5/2015, I spoke with the FBO manager and he advised that he had spoken with the airport manager as well as a person from the construction crew who advised us that we may use Taxiway A after A4 and taxi north west on A until Runway 12. The taxiway was NOTAM'd closed but we used the taxiway upon receiving approval from the airport manager and construction crew and fbo manager. The barricades were moved before our flight by the airport fbo and one other aircraft used the taxiway prior to our use. I entered runway 12 at A2 and back taxied runway 12 until reaching A4. I exited the runway at A4 because there was another aircraft entering the runway to depart runway 12. I was speaking to this other aircraft on the UNICOM on the airport frequency. We continued on Taxiway A while the Co-pilot was performing the appropriate before take-off checklist. My eyes were outside of the airplane, but I do not recall ever seeing the trencher until the co -pilot said "watch that wing". At that point it was too late and impact was made. I do not recall ever seeing the trencher as it was partially blending with the surroundings of the dry brush and the equipment was not flagged or coned off.

An IFR flight plan was filed for KSGU and all NOTAMS for the flight were received before the flight originated.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

Flight crew failed to look outside and remain aware of surroundings at all times. The flight crew must absolutely be certain that someone is always looking outside during taxi to see and avoid all obstructions and hazards. Construction equipment was not properly marked with cones or barriers and flagged appropriately prior to taxiway being opened. Communication was poor between the construction crew and the airport management to allow a closed taxiway to be used by removing the barriers to the closed taxiway.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

300 Gallons**Fuel Type**☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☐ 100 Low Lead☒ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure**

Added 600 gallons of Jet A prior to departure.

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☐ Yes ☒ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location

3 people exited the airplane via the main cabin door.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)**Aircraft Registration Number**

Manufacturer: _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

08/06/2015

mm/dd/yyyy

Name of Pilot/Operator: Jared Ringger

Signature: _____

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

GAA15CA215

Reviewed by NTSB Regional Office

GAA

Name of Investigator

Adam M. Gerhardt

Date Report Received

8/06/2015