



Photo 1 – View of fuselage damage (photo courtesy of the FAA)



Photo 2 - View of fuselage damage from the rear (photo courtesy of the FAA)



Photo 3 - View of fuselage damage from the right side (photo courtesy of the FAA)