



Photo 1 – View of substantial damage to right wing (Courtesy of FAA)



Photo 2 – Top view of substantial damage to right wing (Courtesy of FAA)