



Photo 1 – View of substantial damage to both wings (Courtesy of Operator)



Photo 2 - View of damage to left wing (Courtesy of Operator)



Photo 3 – View of damage to right wing (Courtesy of Operator)



Photo 4 – View of substantial damage to elevator (Courtesy of Operator)