



Photo 1 – View of substantial damage to left wing (Courtesy of Pilot)



Photo 2 – View of substantial damage to aileron (Courtesy of Pilot)



Photo 3 – View of damage to empennage (Courtesy of Pilot)



Photo 4 – View of damage to elevator (Courtesy of Pilot)