



Photo 1 – View of damage to rudder and vertical stabilizer (Courtesy of FAA)



Photo 2 – View of damage to right wing strut (Courtesy of FAA)



Photo 3 – View of damage to left wing struts (Courtesy of FAA)