



Photo 1 – View of damage to right sponson and wing (Courtesy of Operator)



Photo 2 – View of damage to right wing (Courtesy of Operator)