



Photo 1 – Damage to truss structure at the right rear wing root attachment point (Courtesy of FAA)




Photo 2 – Close up of damage to the truss structure at the right rear wing root attachment point (Courtesy of FAA)