



Photo 1 – View of initial impact point and ground scar leading up to main wreckage (photo courtesy of the FAA)



Photo 2 - View of wreckage from the rear (photo courtesy of the FAA)




Photo 3 - View of substantial damage to the firewall (photo courtesy of the FAA)