



Photo 1 – Damage to left aileron (Courtesy of FAA)



Photo 2 – Damage to left aileron and wing (Courtesy of FAA)



Photo 3 – Damage to left elevator and horizontal stabilizer (Courtesy of FAA)