



Photo 1 – View of damage to right wing (Courtesy of FAA)



Photo 2 – View of damage to the firewall (Courtesy of FAA)



Photo 3 – View of damage to the firewall (Courtesy of FAA)