



Photo 1 – View of damage to elevator (Courtesy of FAA)



Photo 2 – View of damage to elevator (Courtesy of FAA)




Photo 3 – View of damaged taxiway sign (Courtesy of Airport Manager)



Photo 4 - View of paint transfer from Maule on to taxiway sign (Courtesy of Airport Manager)




Photo 5 – View of paint and metal transfer from Maule on to taxiway sign (Courtesy of Airport Manager)