



Photo 1 – View of left wing damage from front (report courtesy of the FAA)



Photo 2 - View of left wing damage from rear (report courtesy of the FAA)