



Photo 1 – View of the airplane on the runway with retracted landing gear (Courtesy of FAA)



Photo 2 – View of damage to the bottom of the fuselage (Courtesy of FAA)



Photo 3 – View of damage to the inboard left wing and left aileron (Courtesy of FAA)